Work Orde June-12-13 9:15	r ID 102876 :55 AM	<u> </u>		*102	2876*							Page 1
Item ID: (	546.3301			Accept	*N900	<b>040</b>	100	)*	Setup		1 41	<b>S1</b> *
Item Name:	Upper Cutter Assemb	oly								Stop	*N:	<b>S2</b> *
Start Date: 6 Required Date: 6 Reference:		rt Qty: 10.00 'd Qty: 10.00	*10* *10*		Cust Item I Customer:	D:						
	Process Plan:	MLJ	Date: 13 06-14	Tooling: _ SPC (Y/N):	•	ate:		]		Start Stop	*N  *N	R1* R2*
Sequence ID/ Work Center ID		ration cription	:	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision	Nbr										
646.3300	N/C				1							
*110 *110* Packaging Packaging	Pick l	Kit Memo	•	0.00	13-06-19			e	<u>.                                    </u>			<del></del>
120				0.00	;		* *					
*120* Small Fab		Memo	*	0.00 A	12-0619	•		10		<del></del>		· · · · · · · · · · · · · · · · · · ·
Small Fab			r must be install finger-tight						*. ·			
; «		Assemble as per note 7.	per dwg and apply loctite 5	98 on all faying surface	es shown on dwg							
		A/R RTV L exp. date:	OCTITE 598: 425/	74						•	A CONTRACTOR OF THE PROPERTY O	

DQA:		_ Date:										™ ADT
QA Closed:		Date:			WORK ORDER NON	-C(	ONFO	RMANCE / UPDA		ork Order up	ndate only	AEROSPACE
<del></del>					DISPOSITION			Δ.		PARTMENT	· · · · · · · · · · · · · · · · · · ·	
Work Orde	er:				5.5. 5561	,						
					Rework			<b>├</b> ──	osstube		Water Jet	Engineering
Part N	١٥				Scrap		1	~——	nall Fab	-1	d. Eng. Coor.	Quality
					Use-as-is		Therr	· —	inishing	Rec/Stor	re/Packaging	Other
NCR N	No				Suspected Unapproved	]		Large Fab Con	mposite		Supplier	J LJ
Root				Desci	ription of work order update		Initial	Action		Sign &		
Cause	Date	Step	Qty		or non-conformance	Ch	nief Eng	Description	า	Date	Verification	QC Inspector
Design												
Doc/Data												
Equip/Tooling												
Handling/Pre					,							
Material										, ·		
Operator							V.					
Offset/Setup												
Process						1						
Supplier												
Training												
Transport	_											
Unapproved		<u> </u>				<u> </u>		<u> </u>			_	
						FA	ULT CA	regory	·			
Landir	ng Gear				General	_	;		_	7	•	,
	Bending			-	Bend	$ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{ldsymbol{le}}}}}}$		rogram		Outside Dim	<b>├</b>	Pressure/Forced
	Centre No	ot Concer	ntric	-	BOM/Route		Grain			Over/Under	<del></del>	Set-up
	Cracks			$\vdash$	Broken/Damage/Defect	$\vdash$	Hardwa			Part Incorred	<b>⊢</b>	Temperature/Cure
	Crimp/Kir	nk/Ripple	/Wave	$\vdash$	Burrs	$\vdash$	'	on Incomplete/Unqualif	—	Part Lost/Mi	ssing	Weld
	Cuffs			$\vdash$	Contamination	_	1	ions Incomplete/Unclear	r	Part Moved	L_	Wrong Stock Pulled
	Crushing				Countersink	-	•	ned/off center		Positioned W		,
	Heat Trea			$\vdash$	Cut Too Short	$\vdash$	Mislabe			Power Loss/S	Surge	Other
	Inspectio	٠.	Tube	-	Drawing		Misread	1			<u>.</u>	
	Marks/Ch			-	Drill Holes	$\vdash$	Off-set					
	Turning S				Finish	$\vdash \dashv$	ł	Calibration				
	Wave/Tw	ist in Tuh	10	1 1	Fit/Function		I Out of 9	Coguence				

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH

		2876		*102	876*		····				Page 2
Item ID: Revision ID:	646.3301			Accept	*N900	0401	n	)* Se	etup Stai	14.	S1*
Item Name:	Upper Cutter	Assembly							Sto	<sup>p</sup> *N:	S2*
Start Date:	6/11/13	<b>Start Qty:</b> 10.00	*10*		Cust Item	ID:					
Required Date:	6/11/13	Req'd Qty: 10.00	*10*		Customer:						
Reference:					 			D	un Stai	rt Las	<b>—</b> 4 4
Approvals:	Process Pl	an:	Date:	Tooling:	<u> </u>	Date:				171	R1*
	QC:		Date:	<b>SPC (Y/N):</b>	Г	Date:			Sto	*N	R2*
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	Tool ID		lan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		QC5- Inspect part comple	eteness to step on W/O	0.00				10			
*130* QC Quality Control		Memo		0.00 <b>27</b> 13.6	51.			10			
140		Identify as per dwg & Sto	ock Location: 87.5	440.00	į						
*140* Packaging				0.00				_/OX			
Packaging		Memo ***IDENTIF REV***	Y AS PER APICAL MPP		IE P# AND			-			13-6-
150 *4.50*		QC21- Final Inspection -	Work Order Release	0.00	:				13/6	1259	<b>Y</b>
*150* QC Quality Control		Memo		0.00					1 / [		<b>/</b>

pl 13 04-2 cl

DQA:		_ Date:			•			_					4	<b>DART</b>
QA Closed:		Date:			WORK ORDER NON-	-C(	ONFO	RMANCE / U		W	ork Order u	ndate only		AEROSPACE
arreiosea.		- Date.									·			
Work Orde	er:				DISPOSITION				AGAINST	DE	PARTMENT	PROCESS		
					Rework			Skid-tube	Crosstube			Water Jet	Eng	gineering
Part N	lo				Scrap	] '	1	Machining	Small Fab		Pro	d. Eng. Coor.		Quality
					Use-as-is		Thern	noforming	Finishing		Rec/Sto	re/Packaging		Other
NCR N	lo				Suspected Unapproved	]		Large Fab	Composite		j	Supplier		
Root				Desc	ription of work order update		<u>I</u> Initial	Act	tion		Sign &			
Cause	Date	Step	Qty		or non-conformance	Ch	nief Eng	Desci	ription		Date	Verification	c	C Inspector
Design														
Doc/Data														
Equip/Tooling	_										}	·		
Handling/Pre	_													
Material														
Operator	_										,			
Offset/Setup														
Process														
Supplier									•					
Training														
Transport								-						
Unapproved														
						FA	ULT CAT	TEGORY	·		<del></del>			
Landir	ng Gear				General	_	1		ſ	,	7 .	Г	_	
	Bending	_			Bend	_	-1	rogram	ļ		Outside Dim	<u> </u>	_	ure/Forced
	Centre N	ot Concei	ntric		BOM/Route	<u> </u>	Grain				Over/Under		_ Set-u	
	Cracks			<u> </u>	Broken/Damage/Defect	<u> </u>	Hardwa				Part Incorre	<b>├</b>	- '	erature/Cure
	Crimp/Ki	nk/Ripple	:/Wave		Burrs	<u> </u>	1 .	on Incomplete/Ur	· ·		Part Lost/Mi	ssing	— Weld	
	Cuffs				Contamination	<u> </u>	4	ions Incomplete/U	Jnclear		Part Moved	L	Wron	g Stock Pulled
	Crushing				Countersink	<u> </u>	-1	ned/off center			Positioned V	· ·	٦	
	Heat Trea			-	Cut Too Short	_	Mislabe		Į		Power Loss/	Surge	Other	-
	Inspectio	· · · · · · · · · · · · · · · · · · ·	Tube	_	Drawing	<u> </u>	Misread	1						
	Marks/Cl			_	Drill Holes	<u> </u>	Off-set							
		Sequence		<u> </u>	Finish	_	-	Calibration						
j.	Wave/Tv	vist in Tub	e.	1	Fit/Function	1	1Out of 9	Sequence .						

**Picklist Print** Page 1 June-12-13 9:15:54 AM Work Order ID: 102876 **Start Date:** 6/11/13 Required Date: 6/11/13 Parent Item: 646.3301 **Start Qty: 10.00** Required Qty: 10.00 Parent Item Name: Upper Cutter Assembly IPP REV:A 12.10.19 NEW ISSUE DD VERF:JLM Comments: Status Qty per Kit Total Qty Date Mfg/ Last Unit of Qty.on Component Item ID/ Replacement Bin **Primary** Route Measure Hand Issued Location Issued Item Name Location Seq ID Qty Item ID Purch Item **i** 10 10.0000 1 No Each 10 646.3310 Manufactured 13-06-19 LH Half Loc Oty Loc Code Location 10 ST537 10 110 Each 0.0000 No 646.3311 Manufactured 13-06-19 RH Half 100344 110 Each 10.0000 10 No 646.3312 Manufactured 13-06-19 Center Plate Loc Qty Location Loc Code ST537 10 10 110 10.0000 No Each 10 646.3313 Manufactured 9715-06-19 Upper Guide Loc Qty Loc Code Location st535 10 10 100368 110 10.0000 10 646.3314 No Each Manufactured 15-06-19 Blade Loc Oty Loc Code Location ST139A 10 10 110 Each 10.0000 10 646.3315 Manufactured \$ 13-06-19 Blade Location Loc Oty Loc Code 10 ST139A 100499 10

DQA:		Date:										™ A DT
QA Closed:		Date:			WORK ORDER NON-	-C(	ONFO	RMANCE / UPDATE	W	ork Order up	odate only	AEROSPACE
					DISPOSITION			AGAINS'		PARTMENT	,	
Work Orde	er:				<b>1</b>				_	·	_	· —
					Rework			Skid-tube Crosstube	_	_	Water Jet	Engineering
Part 1	νо				Scrap			Machining Small Fal	-	<b>⊣</b>	d. Eng. Coor.	Quality
N/CD A	d a				Use-as-is	-	Thern	noforming Finishing	_	Rec/Stoi	re/Packaging	Other
NCR I	NO			<del></del>	Suspected Unapproved	]		Large Fab Composite	<u> </u>		Supplier	الا
Root				Desc	ription of work order update		Initial	Action		Sign &		
Cause	Date	Step	Qty		or non-conformance	Ch	nief,Eng	Description		Date	Verification	QC Inspector
Design												
Doc/Data												
Equip/Tooling												
Handling/Pre								. *				
Material				ľ				* 1				
Operator					+	1						
Offset/Setup												
Process												
Supplier												
Training			İ		ł					ł		
Transport						1						
Unapproved						<u> </u>						
<del></del>	<u> </u>			<del></del>	· · · · · · · · · · · · · · · · · · ·	FA	ULT CAT	EGORY				<del></del>
Landi	ng Gear			_	General		1		_	7	F	7
	Bendin	-		<u> </u>	Bend	<u> </u>	1	rogram	_	Outside Dim	<b>├</b>	Pressure/Forced
	—	Not Conce	ntric	<u> </u>	BOM/Route	<u> </u>	Grain		$\vdash$	Over/Under	tolerance	Set-up
	Cracks				Broken/Damage/Defect	<u> </u>	Hardwa		<u>_</u>	Part Incorred	<b>⊢</b>	Temperature/Cure
		Kink/Ripple	e/Wave	<u> </u>	Burrs	<u> </u>	1	on Incomplete/Unqualified		Part Lost/Mi	ssing	Weld
	Cuffs			$\vdash$	Contamination		4	ions Incomplete/Unclear	<b>L</b>	Part Moved		Wrong Stock Pulled
	Crushir	-			Countersink		1 -	ned/off center	_	Positioned W	_	_
	Heat Tr			<u> </u>	Cut Too Short	$\vdash$	Mislabe		L	Power Loss/	Surge	Other
		ion Strip in	Tube	<u> </u>	Drawing	_	Misread	İ				
	_	Chatter		<u> </u>	Drill Holes	-	Off-set					
		Sequence			Finish	-	1	Calibration				
	Wave/	wist in Tul	oe		Fit/Function		Out of S	equence				

## **Picklist Print** Page 2 June-12-13 9:15:54 AM Work Order ID: 102876 **Start Date: 6/11/13** Required Date: 6/11/13 646.3301 Parent Item: Upper Cutter Assembly **Start Qty: 10.00** Required Qty: 10.00 Parent Item Name: 646.3316 1110 Each 10.0000 10 No Manufactured Blade Location Loc Qty Loc Code ST139A 10 10 Each 110 NAS1149FN832P Purchased No 16,568.000 Washer **Location** Loc Qty Loc Code ST294 6568 123522 400 6168 ST510a 10000 125268 10000 180/80 A013-06-19 MS21042L08 No 110 Each 4,201.0000 Purchased Nut Location Loc Qty Loc Code ST315 2201 122141 3 122452 9 122814 500 123900 1689 ST505 2000 125445 2000 gorges . Shop Packet Print Page 2 June-12-13 9:15:54 AM

DQA:			Date:		· · · · · · · · · · · · · · · · · · ·	<u>-</u>							•	<b>™</b> ΛΔRT
QA Closed:			Date:			WORK ORDER NON-	-C(	ONFO	RMANCE / UI		Work Order up	odate only	_	AEROSPACE
Work Ord	ar.					DISPOSITION	-			AGAINST [	DEPARTMENT	/PROCESS		
Part I	No.					Rework Scrap Use-as-is Suspected Unapproved		B .	Skid-tube  Machining  noforming  Large Fab	Crosstube Small Fab Finishing Composite		Water Jet d. Eng. Coor. re/Packaging Supplier		Engineering Quality Other
Root					Desc	ription of work order update		Initial	Act	ion	Sign &		Т	
Cause		Date	Step	Qty		or non-conformance	j	nief Eng		iption	Date	Verification		QC Inspector
Design Doc/Data Equip/Tooling Handling/Pre Material Operator Offset/Setup Process Supplier Training Transport Unapproved														
		_					FA	ULT CAT	TEGORY					
Landi	ng (	1				General	_	٦ .		-		r		
	Ŀ	Bending Centre No Cracks Crimp/Kir Cuffs Crushing	nk/Ripple,			Bend BOM/Route Broken/Damage/Defect Burrs Contamination Countersink		Grain Hardwa Inspecti Instruct Misalig	on Incomplete/Un ions Incomplete/U ned/off center	- H	Outside Dim Over/Under Part Incorred Part Lost/Mi Part Moved Positioned V	tolerance ct ssing Vrong		Pressure/Forced Set-up Temperature/Cure Weld Wrong Stock Pulled
	$\vdash$	Heat Trea			_	Cut Too Short	<u> </u>	Mislabe		L	Power Loss/	Surge		Other
		Inspection		Tube		Drawing	<u> </u>	Misread	I					
	_	Marks/Ch			<u> </u>	Drill Holes	<u> </u>	Off-set						
		Turning S				Finish	<u> </u>	4	Calibration					
		Wave/Tw	ist in Tub	e		Fit/Function	L	Out of S	equence					

June-12-13 9:15:54 AM


Work Order ID:	102876				1		S. A.D.	-4. 6/11/32	D	Date: 6/11/12
Parent Item:	646.3301				!			ate: 6/11/13	_	uired Date: 6/11/13
Parent Item Name:	Upper Cutter Assemb	oly			1		Start (	Qty: 10.00		quired Qty: 10.00
NAS1149F0332P WASHER		Purchased	No		1	Each	11,056.000	6	60	SO 13-06-19
				<u>Location</u>	Loc Oty		Loc Code			·
				GA	18	2				
				122063	18	2		W-144-		
				ST294	15	8			·	
				122063	i 15	8			<del></del>	
				ST295		3				
				123352						
				st510	571					
				123900	571					
				ST510a 125646	500 500			-		
AN3-12A		Purchased	No	123040	110	Each	151.0000	2	20	
Bolt		Fulcilaseu							$\mathcal{Z}^{0}$	90 13-06-19
				Location	Loc Qty		Loc Code			
•				GA		6				
•				122407	1	6				
				ST351	, 14	5				
				114536		1				
				123352		2				
				m125709 (m125752)	, 10 † 4	2			<del></del>	
				11123732	Ì	-				, <del>*</del>
					i s					
					ļ					
					1					
					1					

DQA:			. Date:											$\mathbb{Z} \cap A D T$
						WORK ORDER NON-	-C(	ONFO	RMANCE / U					AEROSPACE
QA Closed:			Date:					<b>,</b>	·····	W	ork Order up	odate only		
Work Orde	er:					DISPOSITION				AGAINST D	EPARTMENT	/PROCESS		
:	-					Rework			Skid-tube	Crosstube	7	Water Jet	$\Box$	Engineering
Part N	10.					Scrap			Machining	Small Fab	Pro	d. Eng. Coor.		Quality
	-					Use-as-is		Therr	noforming	Finishing	<b>⊣</b>	re/Packaging	$\Box$	Other
NCR N	10.					Suspected Unapproved			Large Fab	Composite	1	Supplier		
		•											-	
Root				-	Desc	ription of work order update		Initial	Act	ion	Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	nief Eng	Descr	iption	Date	Verification	1	QC Inspector
Design	$\Box$													
Doc/Data														
Equip/Tooling														
Handling/Pre											,			
Material	_					·							- 1	
Operator	_	,												
Offset/Setup														
Process	$\dashv$													
Supplier	$\dashv$													
Training	$\dashv$											i :		
Transport													l	
Unapproved					<u> </u>				550004					
I		· · · ·	<del></del>				FA	ULI CA	regory			<del></del>		
Landir [					Г	<b>General</b> Bend		]	Program	Γ-	Outside Dim	: [	$\neg$	Danasaya /Farand
•		Bending Centre No	at Cancan	stric		BOM/Route	_	Grain	rogram	-	Over/Under	<b>-</b>		Pressure/Forced Set-up
		Cracks	or concen	ILTIC	-	Broken/Damage/Defect	-	Hardwa	uro	<u> </u>	Part Incorred	· · · · · · · · · · · · · · · · · · ·	_	Temperature/Cure
}	$\dashv$	Crimp/Kir	ak/Pinnla	Mayo	$\vdash$	Burrs	<u> </u>	4	ire ion Incomplete/Un	auglified	Part Lost/Mi	}		Weld
		Cuffs	ik) vibbie,	/ wave	-	Contamination	┝	1 '	•		<b>⊣</b>	22111g		
	-	Crushing			$\vdash$	Countersink	$\vdash$	-1	ions Incomplete/U gned/off center	niclear	Part Moved Positioned V	Vrong [		Wrong Stock Pulled
}	-	Heat Trea	at .		<b> </b>	Cut Too Short	-	Mislabe			Power Loss/	· ·	$\Box$	Other
	-	Inspectio		Tube	$\vdash$	Drawing	-	Misread		L_	J. 5wei 2033/.	Juige [	1	Other
		Marks/Ch	· · · · · · · · · · · · · · · · · · ·		$\vdash$	Drill Holes		Off-set						
·	-	Turning S				Finish		-1	Calibration		-	<del></del>		
•		Wave/Tw		e		Fit/Function		4	Sequence					

June-12-13 9:15:54 AM

Work Order ID:	102876									
Parent Item:	646.3301					Start D	ate: 6/11/13	Req	uired Date:	6/11/13
Parent Item Name:	Upper Cutter Assembly					Start	Qty: 10.00	Red	uired Qty:	10.00
MS21042L3 Nut	Purch	ased No		110	) Eac	ch 2,195.0000	3	30	At .	13-06-19
			Location	<u>L</u>	oc Qty	Loc Code				
	,		FP001		3					
			1221	41	3					
	•		GA		18					
			1224	152	18			<del></del>		
			ST314	<b>1</b>	268					
			1178		32		**-			
			1190		55					
			1190 1232		138 43					
					1906			10		
			ST506 //	1668	954					
			1242	297	952		:2	20	•	
MS27039-08-19 Screw	Purch	ased No		1/10		2,475.0000	18	180	o do	13-06-19
			Location	L.	oc Oty	Loc Code		•		
			ST307	<del></del>	89					
			1235	525	89					
			ST309		1162					
			1256	554	1162		<del></del>			
			st510		1000					
			1243	309	1000					
			ST517		224	a again the first of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same				
			1245	579	224					
AN3-14A Bolt	Purch	nased No		. 11	0 Ea	ach 121.0000	1	10/2	A 13	-06-19
			<u>Location</u>	I	oc Qty	Loc Code				1
			ST351	_	100			•		
				5709	100			<del></del>		
			ST512		21		<del></del>			
			1237	759)	21					
			ت ا							
					<del></del>					

DQA:		Date:						<b>_</b>					™DART
QA Closed:		Date:			WORK ORDER NON-	-C(	ONFO	RMANCE / U		Wor	k Order up	odate only	AEROSPACE
Work Order					DISPOSITION				AGAINST	DEP	ARTMENT	/PROCESS	<del> </del>
Work Order	•	<del></del>			Rework			Skid-tube	Crosstube			Water Jet	Engineering
Part No	o.				Scrap			Machining	Small Fab		Pro	d. Eng. Coor.	Quality
					Use-as-is			noforming	Finishing			re/Packaging	Other
NCR No	o				Suspected Unapproved			Large Fab	Composite		•	Supplier	
Root	<del></del>	l	1	Desc	ription of work order update	<u> </u>	Initial	Λ.σ.	tion		Sign &	· [	
Cause	Date	Step	Qty	Desc	or non-conformance	ı	nief Eng		ription		Date	Verification	QC Inspector
Design	Date	эсер	Qty		or non comormance	-	IICI, LIIB	Desc	TIPCIOTI	+	Date	Vermeation	Qe mspector
Doc/Data													
quip/Tooling	7												
landling/Pre													
Material	7							·					
Operator	-	ŀ											
Offset/Setup													
Process													
Supplier													
Training													İ
Fransport													
Jnapproved					-								
						FA	ULT CAT	regory					
Landing	g Gear				General		_		_				
	Bending				Bend		Folio/P	rogram	į	c	Outside Dim	ensions	Pressure/Forced
	Centre No	ot Conce	ntric		BOM/Route		Grain	·	1		ver/Under	tolerance	Set-up
	Cracks				Broken/Damage/Defect	L	Hardwa	re	<u>]</u>	P	art Incorred	t _	Temperature/Cure
_	Crimp/Kir	nk/Ripple	/Wave		Burrs		Inspect	on Incomplete/U	nqualified	P	art Lost/Mi	ssing	Weld
	Cuffs				Contamination		4	ions Incomplete/	Unclear		art Moved	L	Wrong Stock Pulled
L	Crushing				Countersink		1	ned/off center	1	_	ositioned <b>W</b>		<b>→</b>
<u> </u>	Heat Trea			<u> </u>	Cut Too Short	⊢	Mislabe		į	P	ower Loss/S	Surge	Other
<u> </u>	Inspection	· · · · · · · · · · · · · · · · · · ·	Tube		Drawing		Misread	d		_			· · · · · · · · · · · · · · · · · · ·
_	Marks/Ch			_	Drill Holes	_	Off-set			_			
-	Turning S			<u> </u>	Finish	<u> </u>	4	Calibration		_		•	
	Wave/Tw	ist in Tub	oe		Fit/Function		Out of 9	Sequence					




			ENC	JINE	IERING CHANGE NOTICL NO	. 021	96	SHEET 1 OF 2
	$\Delta$	PICAL	<del></del>		0. 646.3300 REVIN/C BY			0/09 EFFECT ON DWG
IN	DU	STRIES, INC.	ì			UTTER AS:	SY	
			APPRO	VED B	Y, ENGR Some MFG	garde ac	XX	EFF: NEXT ORDER
1 6	-AD	ACTION CODES (TC): D C-CREATE VISE D-DELETE	REA	102 <i>i</i>	REMOVED RIVETS IN FAVOR OF	ADDITIONAL SO	REWSOT	
1.4		EET 1, VIEW 6	46.33		18P_ (10)  2	(a) 36 PL (13) 18PL (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (15) 2P. (	MS27039-0819	
14		601.2765		18	LOCKNUT			para tanan di dagan perangan perangan di dagan perangan di dagan perangan di dagan perangan di dagan perangan d
10 9		601.1541		18	-		MS21042L08 MS20470AD5-18	
-		601.2766			RIVET	<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>		
8	R	601.2764		36	WASHER /		NAS1149FN832P	
				3301	PESCULTION		LA TENTAL ANNENT	T T A T T T N I
		PART NUMBER	QT M		DESCRIPTION  MINSTALL INSTRUC MICA OFMS C	CHANGE BOM DIMENSION	MATERIAL/SPECI CATEGORY DER REN MINOR O YE	VIEW REQUIRED
			···········				<del></del>	


02196


SHEET 2 OF 2


## SHEET 3, SECTION VIEW A-A, IS:



FIN TO PART NUMBER QTY DESCRIPTION MATERIAL/SPECIFICATION










APICAL INDUSTRIES
2608 TEMPLE HEIGHTS DR.
OCEANSIDE, CA., 92056-3512 (760)724-5300


UPPER CUTTER ASSY

SE CAGLOOM ONS 100 646.3300










D



.